



TITLE: TURBOFAN AND MOLD
MANUFACTURING THE SAME
INVENTORS: Jin Baek KIM, et al.
SERIAL NO.: Unassigned
DOCKET NO.: 1594.1311

FIG. 1




TITLE: TURBOFAN AND MOLD
MANUFACTURING THE SAME
INVENTORS: Jin Baek KIM, et al.
SERIAL NO.: Unassigned
DOCKET NO.: 1594.1311

FIG. 2



TITLE: TURBOFAN AND MOLD
MANUFACTURING THE SAME
INVENTORS: Jin Baek KIM, et al.
SERIAL NO.: Unassigned
DOCKET NO.: 1594.1311

FIG. 3



TITLE: TURBOFAN AND MOLD
MANUFACTURING THE SAME
INVENTORS: Jin Baek KIM, et al.
SERIAL NO.: Unassigned
DOCKET NO.: 1594.1311

FIG. 4




FIG. 5





FIG. 6



TITLE: TURBOFAN AND MOLD
MANUFACTURING THE SAME
INVENTORS: Jin Baek KIM, et al.
SERIAL NO.: Unassigned
DOCKET NO.: 1594.1311

FIG. 7

